

Enterprise Services Hours of Service v6.3.3 – Host Production Release Notes

Updated Feb 19, 2024

Contents

Copyright © 2024 Omnitracs, LLC. All rights reserved. This document contains confidential, trade secret, and / or privileged material of Solera and Omnitracs, a Solera company, and may not be shared with anyone outside the intended audience without written approval from Solera.



Compliance – Hours of Service

Improvements

OHOS-13514 – Edit to Driving not displaying distance Fixed an issue where editing duty status to driving and adding the distance driven was not recorded and not displayed in Driver Details.

OHOS-13535 – HOS drivers showing logged in on the website after logging out on the IVG Fixed an issue where drivers in Personal Conveyance appear to be logged in on website despite logging out from IVG.

OHOS-13536 - Edit page error "POI field can't be less than 5 characters" Fixed an issue where editing drivers logs returned error - "POI field can't be less than 5 characters". Admin can now correct an event with an empty/null POI if the event hasn't been auto generated.

OHOS-13563 - Driver receiving out of cycle certification requests after already certifying Fixed an issue where drivers received out of cycle certification requests even after certifying the logs.

OHOS-13580 - Canadian ELD Logs Report showing vehicles not driven Fixed an issue where Canadian ELD logs Report displays power units that were not driven.

OHOS-13465 - Web Services - Host is not updating UpdateTS for newly inactive parent event after driver edit Fixed an issue where Host was not updating the Update time stamp for events edited by the drivers.

Copyright © 2024 Omnitracs, LLC, All rights reserved. This document contains confidential, trade secret, and / or privileged material of Solera and Omnitracs, a Solera company, and may not be shared with anyone outside the intended audience without written approval from Solera.