

Enterprise Services Hours of Service v6.3 – Host Production Release Notes

Updated Jan 04, 2024

Contents

	Service

Copyright © 2024 Omnitracs, LLC. All rights reserved. This document contains confidential, trade secret, and / or privileged material of Solera and Omnitracs, a Solera company, and may not be shared with anyone outside the intended audience without written approval from Solera.

Rev 1.0 - 04.01.2024




Compliance – Hours of Service

New Enhancements

Admin cannot designate UVA as YM/PC

While reviewing the unassigned driving events for vehicles, Admin cannot mark it as 'Yard Move' or 'Personal Conveyance' as per the latest FMCSA regulations.

Admins can only assign unassigned driving as 'Driving', 'Driving (Personal Conveyance)' or 'Driving (Yard Move)'.



Automatically transition driver from Intrastate ruleset to US-Federal/Canada ruleset

When a vehicle crosses a state border, the drivers were prompted to contact the dispatcher to change the ruleset manually. Now the driver will be automatically transitioned from an intrastate ruleset to US Federal ruleset or to Canadian ruleset based on their geo-location.

Now, when a vehicle crosses a state border an alert is triggered automatically notifying the driver of the ruleset change and Admin would no longer be required to change the ruleset manually.

Note: When going from Alaska intrastate to Canada, the driver will be prompted for a Canada operating zone change. When going from Canada to Alaska, the driver will be prompted for USA operating zone change. The Admin will be required to change the driver's ruleset to Alaska.

Copyright © 2024 Omnitracs, LLC. All rights reserved. This document contains confidential, trade secret, and / or privileged material of Solera and Omnitracs, a Solera company, and may not be shared with anyone outside the intended audience without written approval from Solera.

Rev 1.0 - 04.01.2024 2



New Off Duty Deferral Exception Report

Omnitracs Service

Admins can now use the Off Duty Deferral Exception Usage report to identify which driver is using the Off duty Deferral exemption.

Admins can generate this report at a driver level or for a group of drivers.


The report can be downloaded in following formats – CSV, Excel, HTML & PDF.

Description of the fields in the Off Duty Deferral Exception Report -

- Driver Name [Driver Id] Driver ID(s) of the selected driver or group of drivers
- Time Date and Time when the driver uses Off Duty Deferral exception.

Hours of Service Select Other ▼

- Day Indicates which day of the Deferral the driver is operating on (Day 1 or 2)
- Time Suggested Off duty minutes that was suggested by HOS
- Time Deferred Actual off duty minutes the driver defers
- Indicated Less Yes or No, if the driver indicated less deferred time than suggested



Removed the On Duty Rest Break Exemption for Hazmat drivers

Due to 2020 HOS changes we have removed the Hazmat Rest Break exemption from ES HOS Host application. As a result, "Enable Rest Break Exemption for Hazmat Loads" option won't be available on the HOS Setup page within the 'Admin' tab.

Copyright © 2024 Omnitracs, LLC. All rights reserved. This document contains confidential, trade secret, and / or privileged material of Solera and Omnitracs, a Solera company, and may not be shared with anyone outside the intended audience without written approval from Solera.

Rev 1.0 - 04.01.2024




Added visuals to indicate Malfunction on Driver Details page

Admin can easily spot malfunction on a device just by looking at the driver's logs on the Driver Details page.

If a driver's mobile has a malfunction at the time of duty status recording, A will be displayed next to their duty status.

Hover text - 'Malfunction Indicator'



Improvements

Reporting Improvements

OHOS-8286 – HOS Personal Conveyance Report is combining data for drivers with the same name Fixed an issue where Personal Conveyance report is not combining data from different drivers with the same name when selected by driver group.

OHOS-8285 – HOS Yard Move Report is combining data for drivers with the same name Fixed an issue where Yard Move report is not combining data from different drivers with the same name when selected by driver group.

OHOS-7194 - Issue: Varying UA#s in Malfunctions Report

Fixed an issue in Diagnostics & Malfunction report to display ELD events with correct Unit Address details.

OHOS-6765 - Blank pages in HOS Violations report

Fixed the issue with HOS Violations report where extra blank pages are added to the report if the number of records was more than 20.

Copyright © 2024 Omnitracs, LLC. All rights reserved. This document contains confidential, trade secret, and / or privileged material of Solera and Omnitracs, a Solera company, and may not be shared with anyone outside the intended audience without written approval from Solera.

Rev 1.0 - 04.01.2024 4



ERODS Improvements

OHOS-13354 - Unable to submit eRODS

Fixed an issue where ERODS submission was failing due to invalid characters in the driver license number.

OHOS-91 – Customer can't send ERODS for days the driver was in truck shown as AOBRD unit Fixed an issue with ERODS submission where the driver logs contain events from a vehicle that has had the comm unit removed.

API Improvements

OHOS-13103 - DriverLogQueueEx issues

Fixed the issue with DriverLogQueueEx & DriverLogQueueGroupEx API which was crashing due to invalid characters present in the remarks.

OHOS-13312 – DriverLogQueueByGroupEx crashes when French Team Split remark is in the driver's logs Fixed an issue in DriverLogQueueByGroupEx API to ignore Remark field if it has non-printable ASCII characters.

Canadian ELD Improvement

OHOS-13065 - Incorrect end odometer reading on the Canadian ELD Driver Logs Report

Fixed an issue in Canadian ELD driver logs report to display accurate odometer values when the report is run for multiple days.

Other Back-Office Improvements

OHOS-12506 - Customer unable to edit long CSF On-Duty

Fixed the issue with Communication sensor failure (CSF) malfunction events that span for more than a 1 day/week, these events can now be edited by a carrier admin.

OHOS-11369 – Getting Error Report Message in HOS

Fixed an issue in the Hours of Service (HOS) Service Portal, where the user selects "Go to home page" and is redirected to an error message. The user will now return to the home page and no longer get the error message.

OHOS-10109 - Issue: Unable to select "No Carrier"

Fixed an issue on 'Admin-Driver' page where Admin could not select 'No Carrier' option to assign/change carrier for a driver. Selecting 'No Carrier' option would automatically assign default carrier to the driver.

OHOS-7199 - Admin expecting edit button

Fixed an issue where duty status that started outside the 6-month range can be edited.

OHOS-13205 - Remove HOS Vehicle Distance Details Report

We have removed the HOS Vehicle Distance Details Report from the 'Report' tab.

 $Copyright © 2024 \ Omnitracs, \ LLC. \ All \ rights \ reserved. \ This \ document \ contains \ confidential, \ trade \ secret, \ and \ / \ or \ privileged \ material \ of \ Solera \ and \ Omnitracs, \ a \ Solera \ company, \ and \ may \ not \ be \ shared \ with \ anyone \ outside \ the \ intended \ audience \ without \ written \ approval \ from \ Solera.$

Rev 1.0 - 04.01.2024 5