

Fleet portal release notes v9.2.0

Modified on: Fri, 10 Nov, 2023 at 4:14 PM

Fleet Portal

v9.2.0 (2023-11-10)

Enhancements:


1. **Enhanced Mapping and Live View Experience:** New 3rd party maps integration for more aesthetic maps and live view improvements (better current status - live trip, weak signal, etc, ability to view events in ongoing trip, etc.).
2. **Comprehensive Video Request (DVR) Timeline:** Improved visibility into the status of an on-demand video request initiated through the portal (does not apply to requests made earlier)
3. **Global Time Zone Compatibility:** Enhanced timezone support ensures users from around the world can seamlessly utilize the portal according to their local time.
4. **New Traffic Sign Violation Event (BETA):** Introducing the new Traffic Light Violation Safety Event (BETA) which is triggered whenever a driver does not stop at a red light - this works in the US with vertical drop-down lights only.
5. **New Safety Tag 'Workzone (BETA)':** Introducing a new safety tag, 'Workzone (BETA),' which will now be displayed under Speed Limit Violation when the event occurs in a work zone as indicated by a speed limit sign with an orange stripe.

Bug Fixes:

1. **Coaching Configurations:** Resolved the issue related to the Seatbelt event shown under the road-facing category.

Reference Screenshots:

- Home
- Safety Events
- Trips
- Live View
- Coaching
- Video Requests
- Drivers
- Challenges
- Reports
- Assets
- Users
- Configurations



Search By Asset ID

Enter Asset ID

Asset ID

353376110052468



864281040458102



864281041516544



asset009-Mitac



asset009-Mitac1



fc-modified-ircut



fc-modified-ircut1



KrishnaSX4



Krushika-WagonR



mithun-jc400



1-10 / 12



© Mapbox © OpenStreetMap Improve this map

- Home
- Safety Events
- Trips
- Live View
- Coaching
- Video Requests
- Drivers
- Challenges
- Reports
- Assets
- Users
- Configurations

Video Requests

Easily view status timeline

Request Status Timeline

View the status timeline of the video request along with the details

ASSET ID
SOU MIK-i10VIDEO START TIME
17/10/2023 15:52:46DRIVER ID
Soumik UkilDURATION
10 minutes

Current Status: READY

STATUS TIMELINE

- Notification received by the camera
19/10/2023 16:25:45
- Video processing successful
19/10/2023 16:26:01
- Video upload completed, ready to view now
19/10/2023 16:26:23

Request Created

19/10/2023 12:16:11

19/10/2023 10:43:07

19/10/2023 10:42:51

19/10/2023 10:42:37

18/10/2023 14:46:32

Prasad

READY

17/10/2023 15:13:08

5 minutes

Soumik Ukil

SOU MIK-i10



Items per page: 5

1-5 / 12



Date Range

2023 - 20/10/2023

Select Tags

SEARCH



Video Requests

Panic Button

Event On-Demand

Applicable for older requests).

Asset ID

Actions

Soumik Ukil

SOU MIK-i10

Soumik Ukil

SOU MIK-i10

Soumik Ukil

SOU MIK-i10

Soumik Ukil

SOU MIK-i10

Soumik Ukil

SOU MIK-i10

Soumik Ukil

SOU MIK-i10

Soumik Ukil

SOU MIK-i10

Soumik Ukil

SOU MIK-i10



Soumik Ukil

SOU MIK-i10


Soumik Ukil

SOU MIK-i10


Soumik Ukil



Speed Limit Violation Workzone (BETA)



2023-10-16 13:38:32 lat:12.879947 long:77.494392 speed:80.0kmph speed-sign:60




2023-10-16 13:38:32 lat:12.879947 long:77.494392 speed:80.0kmph speed-sign:60

Time - 16/10/2023 13:38:39

Driver - Mithun

Asset ID - asset009-Mitac1



mapbox © Mapbox © OpenStreetMap

DISCARD EVENT SELECT FOR COACHING

Figure 10 displays four screenshots of the 'Speed Limit Violation' app interface, showing speed limit violations for a vehicle with license plate 16/10/2023 13:02:29. The app displays the speed limit (50 km/h) and the vehicle's speed (50 km/h).